

LEICA BLK2GO

HANDHELD IMAGING LASER SCANNER

RELEASE NOTES

FIRMWARE VERSION 1.1.0 – 25th SEPTEMBER, 2020

These Release Notes contain important information about the Leica BLK2GO new firmware version 1.1.0.

It is highly recommended to always use the latest version of the BLK2GO firmware, the BLK2GO Live app and Cyclone software.

The firmware can be downloaded from the Leica myWorld customer portal as well as from the website <https://shop.leica-geosystems.com/blk2go-firmware>.

WHAT'S NEW

- Device general performance and stability improvements.
- SLAM performance and stability improvements.
- Static initialization improvement. This fixes certain data quality issues that could occur after processing. It is still recommended to firmly hold the BLK2GO on the table stand while initializing (yellow blinking).
- Slight increase of the fan speed to help reduce the device temperature. That leads to a slightly different noise level.

Downgrading to a previous firmware version is not recommended. In case you still would like to install a previous firmware version, please get in contact with your local support for assistance.

For details on how to update the firmware version on the BLK2GO, see the firmware guide available on Leica myWorld and BLK2GO websites.

For additional support, please contact your local reseller for first level support.

LEICA BLK2GO

HANDHELD IMAGING LASER SCANNER

RELEASE HISTORY

FIRMWARE VERSION 1.0.10 – 16th JUNE, 2020

FIRMWARE VERSION 1.0.8 – 24th MARCH, 2020

FIRMWARE VERSION 1.0.7 – 7th FEBRUARY, 2020

