

LEICA BLK2GO

HANDHELD IMAGING LASER SCANNER

RELEASE NOTES

FIRMWARE VERSION 2.0.1 – 30th MARCH, 2021

These Release Notes contain important information about the Leica BLK2GO new firmware version 2.0.1.

It is highly recommended to always use the latest version of the BLK2GO firmware and the BLK2GO Live app. For compatibility reasons, please use firmware version 2.0.1 with BLK2GO Live app version 1.2.5 (iOS) and 1.0 (Android) or later. There is no backward compatibility of BLK2GO firmware 2.0.1 with previous versions of Cyclone. For compatibility reasons, please use BLK2GO firmware version 2.0.1 with Cyclone REGISTER 360 v.2021 and Cyclone REGISTER 360 (BLK Edition) v.2021 or later.

The firmware can be downloaded from myWorld @ Leica Geosystems customer portal as well as from the website <https://shop.leica-geosystems.com/blk2go-firmware>.

BUG FIXES

- Fix a LiDAR issue that happened when scanning outdoor in sunlight conditions that was causing the scan to stop. The system is now more resilient to sunlight.
- Fix a rare issue which previously led to live companion app preview freezing, while scan continued without indication of issue.
- Fix an issue where LED status on the BLK2GO was not in synch with the BLK2GO Live app during initialisation.
- Improve battery detection.
- General system stability improvements.

For details on how to update the firmware version on the BLK2GO, see the firmware guide available on myWorld @ Leica Geosystems customer portal and BLK2GO website.

For additional support, please contact your local reseller for first level support.

LEICA BLK2GO

HANDHELD IMAGING LASER SCANNER

RELEASE HISTORY

FIRMWARE VERSION 2.0.0 – 11th FEBRUARY, 2021

FIRMWARE VERSION 1.1.2 – 18th DECEMBER, 2020

FIRMWARE VERSION 1.1.1 – 27th NOVEMBER, 2020

FIRMWARE VERSION 1.1.0 – 25th SEPTEMBER, 2020

FIRMWARE VERSION 1.0.10 – 16th JUNE, 2020

FIRMWARE VERSION 1.0.8 – 24th MARCH, 2020

FIRMWARE VERSION 1.0.7 – 7th FEBRUARY, 2020

