

LEICA BLK2GO

HANDHELD IMAGING LASER SCANNER

RELEASE NOTES

FIRMWARE VERSION 2.0.3 – 30th SEPTEMBER, 2021

These Release Notes contain important information about the Leica BLK2GO new firmware version 2.0.3.

This is a technical release that adds support for newer hardware revisions. Besides the added support for revised internal components, it is otherwise identical to 2.0.2. However, the new hardware revision is introduced with serial number 3631167. With this serial number and above, this firmware version or newer will be required. Earlier devices may be updated, but will see no benefit.

The firmware can be downloaded from myWorld @ Leica Geosystems customer portal as well as from the website <https://shop.leica-geosystems.com/blk2go-firmware>.

For details on how to update the firmware version on the BLK2GO, see the firmware guide available on myWorld @ Leica Geosystems customer portal and BLK2GO website. For additional support, please contact your local reseller for first level support.

LEICA BLK2GO

HANDHELD IMAGING LASER SCANNER

RELEASE HISTORY

FIRMWARE VERSION 2.0.2 – 17th JUNE, 2021

FIRMWARE VERSION 2.0.1 – 30th MARCH, 2021

FIRMWARE VERSION 2.0.0 – 11th FEBRUARY, 2021

FIRMWARE VERSION 1.1.2 – 18th DECEMBER, 2020

FIRMWARE VERSION 1.1.1 – 27th NOVEMBER, 2020

FIRMWARE VERSION 1.1.0 – 25th SEPTEMBER, 2020

FIRMWARE VERSION 1.0.10 – 16th JUNE, 2020

FIRMWARE VERSION 1.0.8 – 24th MARCH, 2020

FIRMWARE VERSION 1.0.7 – 7th FEBRUARY, 2020

